


SmartLink Aircard Error Troubleshooting Chart



Weathermatic™

**Weathermatic Tech Support
888-484-3776 option 1**



Tools You Will Need

- (1) Spare SmartLine panel
- (1) 1.0 slow blow fuse (for SL1600)
- (1) 1.5 slow blow fuse (for SL4800)
- (1) Spare SLW5
- (1) SL-HIGHGAIN-ANT-WB-3

Weather Station Reset Procedure

- (1) Remove weather station and hub
- (2) Create Snapshot in Smartlink
- (3) Perform a CLR ALL under ADVANCED menu on the controller
- (4) Power cycle the controller
- (5) Install new SLW5 and hub
- (6) Send the Snapshot from SmartLink

*If SmartLine Solar model, see Solar Troubleshooting Chart